

# Department of EEE EE8401 –Electrical Machines-II Unit III - MCQ Bank

1. The difference between the stator synchronous speed and rotor speed is called

- A. Leading speed
- B. Lagging speed
- C. Slip Speed
- D. Slow Speed

Answer: C

2.In three phase induction motor maximum torque is Inversely Proportional to the Stator Voltage

- A. Speed of Rotor
- **B.** Rotor Reactance
- C. Decreasing Slip speed

Answer: B

3.No-Load test on an induction motor is conducted to find which of the following losses?

- A. Stator core loss
- B. Rotational Loss
- C. Stator Copper loss
- **D.** All of the above

Answer: D

4. If the torque of the induction motor decreases the\_\_\_\_\_

# A. Speed of the rotor Increases

- B. Speed of the Rotor Decreases
- C. The current of the Rotor Decreases
- D. Power of the Motor Increases

Answer: A

5. Find the number of poles required, if the frequency is 50Hz and speed of the motor is 500 rpm.

- A. 24 Poles
- B. 12 poles
- C. 5 Poles
- D. 10 Poles

Answer: B

6.In squirrel cage induction, the rotor slots are slightly skewed in order to reduce

- A. Windage Loss
- B. Eddy current Loss
- C. Reduce Magnetic humming
- D. Friction losses

# Answer: C

- 7. Low-frequency supply is obtained by
  - A. Motor-generator set
  - B. Frequency changer
  - C. Either Motor-generator set or Frequency changer
  - D. Both Motor-generator set or Frequency changer

Answer: C

8. What type of operate a direct-on-line starter consists of a coil operated

A. Capacitor operated

# **B.** A coil Operated

- C. Eddy current Operated
- D. Resistor Operated

Answer: B

9.Rotating magnetic fields are also used in 3-phase induction motors rotor developing

# A. Eddy current

- B. Voltage Lag
- C. Load current
- D. Phase current

#### Answer: A

10.One of the speed control methods of a 3 phase induction motor is

- A. V/F control
- B. Stator current control
- C. Core loss control
- D. Eddy current Control

Answer: A

11.If the air gap in an induction motor is increased\_\_\_\_\_

A. The speed of the rotor increases

# **B.** The power factor will decrease

- C. The windage losses will increase
- D. Current drawn by the motor increase

#### Answer: B

12.In three-phase induction motor reversing the supply in two of the phases is called as

- A. Pole changing
- **B.** Plugging
- C. increase the torque
- D. To control current

Answer: B

13. The availability of full -rated torque at starting is obtained from an induction motor is

#### A. Rotor resistance control

- B. Stator voltage control
- C. Slip ring control
- D. Line current control

Answer: A

14.Why is the rotor skewed?

- A. To prevent starting current
- B. To provide stability
- C. To reduce magnetic turn
- **D.** To reduce rotor locking tendency

Answer: D

15. The speed of the motor for the frequency of 60 Hz and 4 poles motor is?

- A. 3600 rpm
- B. 1800 rpm
- C. 1500 rpm
- D. None of these

Answer: B

16.A 3 phase, 400-V, 50 Hz 4 pole induction motor is fed from a 3-phase supply and runs of 1425 rpm. The frequency of the rotor emf is

- A. 2.5 Hz
- B. 50 Hz
- C. 48 Hz
- D. Zero

Answer: A

17.In the case of traveling cranes, the motor preferred for boom hoist is \_\_\_\_\_

- A. Slip Ring Induction Motor
- B. Squirrel cage induction motor
- C. Synchronous Motor
- D. Single-phase motor

Answer: A

18. The purpose of skewing of rotor slots in an induction motor is to\_\_\_\_\_\_

- A. Reduce magnetic hum
- B. Increase the distribution factor
- C. Reduce the locking tendency of the rotor
- D. Increase the air gap

Answer: C

19.In motor circuit static frequency changers are used for \_\_\_\_\_

- A. Power factor improvement
- **B.** Speed regulation
- C. Improve cooling
- D. Reversal of direction

Answer: B

20.NEMA standards rate motors according to\_\_\_\_\_

- A. Weight
- B. Horsepower
- C. Voltage
- **D.** Frame

Answer: B

21. What is the maximum length of the flexible conduit in the motor installation?

A. More than 5 meter

B. Less than 1.25 meter

- C. Less than 2.25 meter
- D. Less than 3.25 meter

Answer: B

22.A three-phase induction motor is analogous to

- A. Generator
- **B.** Rotating transformer
- C. Rotating Motor
- D. Rotating converter

Answer: B

23.For the production of induced e.m.f, the field system of an electric machine\_\_\_\_\_.

- A. Must be on the rotor
- B. Must be on the stator
- C. May be on rotor and stator
- D. None of the above

Answer: C

24.15 minutes rated motors are suitable for

- A. Light duty cranes
- B. Medium duty
- C. Heavy-duty cranes
- D. All option are correct

Answer: A

25. The speed of the rotating magnetic field in an induction motor is known as the

# A. Synchronous speed

- B. Shaft speed
- C. Slip speed
- D. Effective speed

Answer: A

26.Light duty cranes are generally used in

- A. Automobile workshop
- B. Pumping Station

C. Power Houses

# **D.** All of the above

# Answer: D

27.In an induction motor, if the rotor resistance is equal to stand-still reactance then the maximum torque is

# A. Equal to starting torque

- B. Less than the starting torque
- C. More than the starting torque
- D. None of these

Answer: A

28. Why is the air gap between the yoke and armature of an electric motor kept smaller?

# A. To achieve a stronger magnetic field

- B. To avoid overheating of the machine
- C. To make the station easier
- D. None of these

Answer: A

29. What is the effect produced by the electric current in an electric motor?

- A. Magnetic effect only
- B. Magnetic as well as the heating effect
- C. Heating effect only
- D. Heating as well as the chemical effect

Answer: B

30.If the stator voltage of a squirrel cage induction motor is reduced to 50 percent of its rated value, the torque developed is reduced by how many percentages of its full load value?

- A. 50%
- B. 25%
- C. 75%
- D. 57.7%

Answer: C

31. The shaft of an induction motor is made of

- A. Stainless steel
- B. Carbon steel
- C. Cast iron
- D. Aluminium

Answer: B

32. Slip ring of an induction motor is usually made up of

- A. Aluminium
- B. Copper
- C. Phosphorus Bronze

D. Carbon Answer: C

33. A 3-phase 440 V, 50 Hz induction motor has 4% slip. The frequency of rotor current will be

- A. 50 Hz
- B. 25 Hz
- C. 5 Hz
- D. 2 Hz

Answer: D

34. The starting torque of a squirrel-cage induction motor is

- A. Full-load torque
- B. Slightly more than full-load torque
- C. Low
- D. Negligible

Answer: D

35. The efficiency of an induction motor is about

- A. 100%
- **B. 80-90%**
- C. 50-60%
- D. Less than 50%

Answer: B

36. A double squirrel-cage induction motor has

- A. Two series winding in stator
- B. Two parallel windings in stator
- C. Two parallel winding in Rotor
- D. Two rotors moving in opposite direction

Answer: C

37. For starting of an induction motor, star/delta starting can be considered equivalent to an autotransformer starter with the ratio of

- A. 33.3%
- B. 50%
- C. 100%
- D. 57.7%

Answer: D

38.An induction motor is analogous to

A. Auto-transformer

# **B.** Two windings transformer with secondary short circuited

- C. Two windings transformer with secondary open circuited
- D. Synchronous motor

Answer: B

39. No load test of 3-phase induction motor used to determine

- A. Variable loss
- **B.** Constant loss
- C. Eddy current loss only
- D. Hysteresis loss only

Answer: B

40. Blocked rotor test in an induction motor is used to determine

- A. Leakage impedance
- B. Copper loss

C. Both 1 & 2

D. None of the above

Answer: C

41. Which of the following losses are negligible in blocked rotor test?

A. Mechanical losses

B. Iron losses

C. Both 1 & 2

D. None of the above

Answer: C

42. The rotor power output of a 3-phase induction motor is 30 KW and corresponding slip is 4%. The rotor copper loss will be

- A. 625 Watt
- B. 250 Watt
- C. 1000 Watt
- **D. 1250 Watt**

Answer: D

43. In an induction motor if the air gap is increased than which of the following statement is correct

- A. Power factor will decrease
- B. Power factor will increase
- C. Speed will increase
- D. Speed will decrease

Answer: A

44. If the applied rated voltage per phase is reduced to one-half, then the starting torque of squirrel cage induction motor becomes

- A. 4 times the initial value
- B. 2 times the initial value
- C. 1/4 of the initial value
- D. 1/2 times the initial value

Answer: C

45. The value of power factor of an induction motor operating at no load is

- A. 0.9 lagging
- B. Unity

C. 0.2 lead **D. 0.2 lag** Answer: D

46. What is the ratio of rotor input power to rotor copper loss in an induction motor?

- A. 1/(1-S)
- B. 1 S
- C. 1/S
- D. S

Answer: C

47.Semi closed slots or totally closed slots are used in induction motors to improve

- A. Starting current
- B. Starting Torque
- C. Power Factor
- D. Pull-out Torque

Answer: C

- 48. The rotor slots are slightly skewed in squirrel cage induction motor in order to A. Increasing Rotor bar strength
  - B. Prevent cogging effect
  - C. Both 1 & 2
  - D. None of the above

Answer: B

49. If an induction machine is run at above the synchronous speed it acts as

- A. Synchronous Motor
- B. Synchronous Generator
- **C. Induction Generator**
- D. None of the above

Answer: C

50. The best method to increase the starting torque of a 3-phase slip ring induction motor is

#### A. Rotor Resistance

- B. Supply voltage
- C. Supply Frequency
- D. None of the above

Answer: A

51. A small air gap in 3 phase induction motor helps to

- A. Reduce cogging effect
- B. Reduce Crawling effect

# C. Reduce Magnetizing effect

D. All of the above

Answer: C

52. In case of induction motors the ratio of core length to pole pitch for minimum cost is taken as

A. 2-3B. 1.5-2

- C. 3 5
- D. 4–6

# Answer: B

53. In an induction motor, there is decrease in maximum power factor when the dispersion coefficient is

- A. Remain Same
- B. Decreased
- C. Constant

# **D.** Increased

Answer: D

# 54. Induction motors have the advantage of

- A. Less Maintenace
- B. Less cost
- C. Simple in construction

# **D.** All of the above

Answer: D

55. What happens if fifth harmonics is given to induction motor?

A. Short-circuit the motor

# **B.** Motor will rotate in reverse direction

- C. Motor will rotate in the same direction
- D. None of the above

Answer: B

56. The maximum EMF is induced in the rotor of a 3-phase induction motor when it

- A. No-Load
- B. Full-load
- C. Half-load
- D. is blocked

Answer: D

57. The power supplied to a three-phase induction motor is 32 kW and the stator losses are 1200 Watt. If the slip is 5 percent. determine the rotor copper loss

- A. 2.8 kW
- B. 3.5 kW
- C. 4 kW

# **D.** 1.54 kW

Answer: D

58. From the above question find the total mechanical power developed by the Rotor

- A. 30.28 kW
- B. 29.26 kW
- C. 25.2 kW
- D. 14.45 Kw

E. Answer: B

59. Find the efficiency of the induction motor neglecting rotor iron loss.

- A. 100 %
- B. 50%
- C. 25%
- D. 89%

Answer: D

**60.** If the stator voltage of a squirrel cage induction motor is reduced to 50 percent of its rated value, the torque developed is reduced by how many percentages of its full load value?

- A. 50%
- B. 25%
- C. 75%
- D. 57.7%

Answer: C

61. The rotor current in a 3-phase induction motor is ...... slip.

- A. Directly proportional to
- B. Inversely Proportional to
- C. Independent
- D. None of the above

Answer: A

62. At starting, rotor reactance of a 3-phase induction motor is ..... as compared to rotor resistance.

- A. Small
- B. Equal to
- C. Large
- D. None of the above

Answer: C

63. When an induction motor is running at full-load, rotor reactance is ..... rotor resistance.

- A. Very large
- B. Large
- C. Comparable
- D. None of the above

Answer: C

64. If the slip of a 3-phase induction motor increases, the p.f. of the rotor circuit is

# A. Decreased

- B. Remain unchanged
- C. Increased
- D. None of the above

Answer: A

65. The magnetising current drawn by a 3-phase induction motor is about ..... of full-load stator current.

A. 30 – 50 %

- B. 15 20%
- C. 10 15%

D. 5% Answer: A

66. The value of load current of 3 phase induction motor is \_\_\_\_\_ of full load current

- A. 25 35 %
- B. 5 10%
- C. 2 4%
- D. None of the above

Answer: A

67. The starting torque of a 3-phase induction motor is ..... supply voltage.

- A. Independent of
- B. Directly proportional
- C. Directly proportional to square
- D. Inversely proportional

Answer: C

68. The starting torque of an induction motor is maximum when rotor resistance per phase is ...... rotor reactance/phase.

- A. Equal to
- B. Less than
- C. More than
- D. None of the above

Answer: A

69. The maximum torque of a 3-phase induction motor under running conditions is

# A. Inversely proportional to the Rotor reactance at standstill

- B. Inversely proportional to the supply voltage
- C. Directly proportional to the Resistance
- D. None of the above

Answer: A

70. If the supply voltage of a 3-phase induction motor is increased two times, then, torque is

# A. Increased 4 times

- B. Decreased 4 Times
- C. Increased twice
- D. Remain the same

Answer: A

71. The 3-phase induction motor is so designed that the rotor should have ..... under running conditions.

- A. High resistance
- **B.** Low resistance
- C. Large slip
- D. High reactance

Answer: B

72. If a 3-phase induction motor is running at slip s, then, rotor copper loss is equal to.

- A.  $(1 s) \times \text{Rotor Input}$
- B.  $(1 + s) \times \text{Rotor input}$
- **C.** s × **Rotor input**
- D.  $s \times stator input$

Answer: C

73. If an induction motor is running at slip s, then rotor output is

- A.  $(1 s) \times Rotor input$
- B.  $(1 + s) \times \text{Rotor input}$
- C.  $s \times Rotor input$

D. None of the above

Answer: A

74. If the motor were to run at 65% speed as in 'the given above question, but operate as a 6 pole machine, what will be the slip and frequency of the rotor currents?

- A. 4.175 Hz
- B. 3.286 Hz
- C. 2.458 Hz
- D. 1.432 Hz

Answer: A

75. For a slip of 0.05, find the ratio of rotor speeds with the motor operating with 4 and 6 poles respectively.

- A. 2.8
- **B.** 1.5
- C. 3.2
- D. 4.5

Answer: B